E
5/24/89

100 EAST 42 STREET
NEW YORK, N.Y. 10017
PHONE: (212)697-3600

NORTH AMERICAN PHILIPS CORPORATION

EXECUTIVE OFFICES

May 24, 1989

Mr. Kenneth M. Theisen
Environmental Scientist
U.S. Environmental Protection Agency
Region V
230 S. Dearborn Street
Chicago, IL 60604

Re: The Selmer Company
Elkhart, IN

Dear Mr. Theisen:

Attached please find three copies of the soil boring test results for The Selmer Company in Elkhart, IN. These are the results of the sampling activities which you witnessed on April 26 and 27, 1989.

I look forward to discussing these test results with you at our meeting on May 25, 1989.

Thank you for your attention.

Sincerely,

Ann C. Pizzorusso

Ann C. Pizzorusso
Director
Environmental Affairs

Attach.

TABLE 1
Selmer Band Instruments
Elkhart, Indiana
Preliminary Assessment Analytical Results

SAMPLE LOCATION (EMS Sample No.)	RESULTS*	
Sample 1 (3.0 - 3.5') (122746)	Methylene Chloride	.87
	Xylenes	1.2
	Trichloroethene	11.0
Sample 1 (~8') (122747)	Trichloroethene	9.1
Sample 2 (2.5') (122748)	Trichloroethene	.50
Sample 2 (8.0') (122749)	Trichloroethene	1.4
Sample 2 (14.0-14.5') (122750)	Trichloroethene	(0.25)
Sample 3 (6') (122751)	Methylene Chloride	.60
	Xylenes	.59
Sample 4 (5') (122752)	ND	
Sample 5 (0.5 - 1.5') (122753)	Methylene Chloride	.77
	1,2-Dichloroethene	1.1
Sample 5 (7.0 - 8.5') (122754)	ND	
Sample 6 (7.0 - 8.5') (122755)	ND	
Sample 6 (13') (122756)	Methylene Chloride	.65
	Xylenes	.55
Sample 7 (4') (122757)	Methylene Chloride	.61
	Trichloroethene	4.9
	Xylenes	.79

TABLE 1
(Continued)

Sample 7 (9') (122758)	Acetone Methylene Chloride Trichloroethene Xylenes	1.6 1.1 .49 1.2
Sample 7 (10.0-11.5') (122759)	ND	
Sample 8 (11.5 - 13.0') (122760)	Methylene Chloride Trichloroethene Xylenes	.62 1.9 1.1
Sample 9 (6.5 - 8.0') (122761)	Methylene Chloride	.51
Sample 9 (11.0 - 12.5') (122762)	Methylene Chloride Xylenes	.77 .88
Sample 10 (0 - 2') (122763)	Methyl ethyl ketone	1.2
Sample 10 (2 - 4') (122764)	Methyl ethyl ketone	.71
Grab Sample (Shallow ground water) (122765)	1,2-Dichloroethene (total) Trichloroethene Vinyl Chloride	490 uG/L 160 uG/L 35 uG/L
Decon Water Composite (122774)	Trichloroethene	10.0 uG/L

(.25) = Estimated concentration, below methods detection limits

* All results in mg/kg, unless otherwise indicated.

ND = No compounds detected by RCRA volatiles scan (Method SW846-8240).

DO89529.D



SAMPLE LOCATION PLAN

= BORING/SAMPLE LOCATION

HERITAGE REMEDIATION/ENGINEERING INC.

(NORTH AMERICAN PHILLIPS)

SELMER BAND INSTRUMENTS

ELKHART, IN

SCALE: 3/4"=10'

89058160 JFH5/2/89



SAMPLE LOCATION PLAN

● = BORING/SAMPLE LOCATION

HERITAGE REMEDIATION/ENGINEERING INC.

(NORTH AMERICAN PHILLIPS)

SELMER BAND INSTRUMENTS

ELKHART, IN

SCALE = SCHEMATIC

DA089058160 JFH5/18/89

TABLE 2
(Continued)

Boring/Sample	Reading* (ppm as CH_3)
#7 (4.0-5.5')	22.0
#7 (5.5-7.0')	5.6
#7 (7.0-8.5')	12
#7 (8.5-10.0')	34
#7 (10.0-11.5')	40
#7 (11.5-13.0')	.6
#8 (1.0-2.5')	5.0
#8 (2.5-4.0')	4.6
#8 (4.0-5.5')	4.4
#8 (5.5-7.0')	4.4
#8 (7.0-8.5')	No recovery
#8 (8.5-10.0')	4.8
#8 (10.0-11.5')	4.6
#8 (11.5-13.0')	4.6
#9 (5.0-6.5')	4.2
#9 (6.5-8.0')	4.0
#9 (8.0-9.5')	4.0
#9 (9.5-11.0')	4.0
#9 (11.0-12.5')	4.0
#10 (0-2')	4.4
#10 (2-4')	4.6
Grab Sample (open hole)	3.8

*Ambient OVA readings ranged from 3.2-6.0